


OMTER OM-104



Instruction for choosing model:

M1: The potentiometer is 5K Ohm, Maximum from 1.8KΩ±5% to 3.2KΩ±5%

M2: The potentiometer is 5K Ohm, Maximum from 0 to 5KΩ±5%

M3: The potentiometer is 10K Ohm, Maximum from 6.5KΩ±5% to 3.5KΩ±5%

M4: The potentiometer is 10K Ohm, Maximum from 0 to 10KΩ±5%

